

STEERING RACK SURCHARGE POLICY

Returning your exchange unit does not guarantee refund of the surcharge.

Your surcharge will only be refunded once the rack has been stripped and we have ascertained that it is a serviceable unit.

This is because we frequently encounter problems with corrosion to the central shaft and excessive wear in the pinion.

Please ensure that your exchange unit is drained of fluid and that all pipes, unions and banjo bolts are still fitted and undamaged.

If you are unsure about this policy, please call prior to fitting the reconditioned unit.