



DATA INFORMATION SHEET FOR THE PISTON RING KIT & SET

PART NO: RINGKIT-1 & RINGSET-1

In 2005, Bentley Motors authorised Peter Hepworth to redesign the piston and ring assemblies for the early V8 engines.

This involved minor amendments to some of the measurements, material and manufacturing processes.

Please be aware that the Workshop Manual (TSD2476) specifies a closed ring gap of **0.015" - 0.020"**.

The redesigned top rings UE5691P have a specified gap of **0.01574" - 0.02559"**.

The oil control rings UE33334 have a specified gap of **0.0118" - 0.0236"**.