

# Otter Switch - Solenoid Weakener Valve

## Applicable to

All Rolls-Royce Silver Shadow, Corniche and Camargue and all Bentley Corniche and Bentley T series cars.

## Introduction

This Product Support Information Sheet has been issued to describe the fitting procedure for the replacement of the solenoid weakener valve otter switch UE 39592 which is no longer available, with otter switch **UE 43197**.

## Description

The latest otter switch can be fitted to the cars identified in the section entitled Applicable to'.

## Procedure

- 1. Disconnect the defective otter switch and remove together with the gasket and screws.
- 2. Clean the area thoroughly making sure all of the residual gasket and any grease is removed.
- 3. Fit three cap head screws incorporating a thread, fastener such as Loctite 270, Stud lock or 242 Nutlock, being careful to observe the manufacturer's instructions.
- 4. Press in the rubber bush ensuring that the flange of the bush is fully pressed down to the machined surface.
- 5. Fit the new otter switch ensuring that it is pushed in firmly and reconnect the electrical connections.

## Parts Affected

Displaced part number	New part numbers	Quantity
UE 39592	<b>UE 43197</b> Otter switch	1
	SPC 2752 Mounting bush	1
	UA 7482 Cap screw	3